

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Casey, William**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-029538**Date Inspected:** 26-Apr-2013**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1730**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Jobsite**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

At the start of shift, this Quality Assurance Inspector (QAI) traveled to the project site and observed the work and the inspection performed by American Bridge/Fluor Enterprises (AB/F) personnel. The inspection was performed on the various Complete Joint Penetration (CJP) groove welds of the East and West Orthotropic Box Girders (OBG's).

The welding was performed utilizing Shielded Metal Arc Welding (SMAW) process as per the Welding Procedure Specifications (WPS's).

This QAI witnessed welding of the socket welds of a 1-inch diameter air vent pipe stubs to 90 degree elbows for Bikepath locations: 6-AV1-PFP-BE, 5-AV1-PFP-BE, 7-AV1-PFP-BE, 8-AV1-PFP-BE. This QAI also witnessed welding of 1 inch diameter air vent pipe stub to 45 degree elbow for Bikepath location 9-AV1-PFP-BE. F.W. Spencer welder Rick Kickvee #5319 performed the welding utilizing E7018 electrodes as per WPS #1-12-1. AB/F QC Fred Michels was present.

Summary of Conversations:

At the start of the shift there were general conversations with field inspector, Sal Merino, regarding the location of welding, inspection and N.D.E. testing personnel scheduled for this shift.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact SMR Gary Thomas (916) 764-6027, who represents the Office of Structural

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Materials for your project.

Inspected By: Morris, Monty

Quality Assurance Inspector

Reviewed By: Reyes, Danny

QA Reviewer